



THE UNIVERSITY OF TEXAS SYSTEM

University Lands

www.utlands.utsystem.edu

P. O. Box 553
Midland, Texas 79702

Tel: (432) 684-4404
Fax: (432) 687-1812

Well Status Change

Current Status: Producing Operator: Endeavor Energy

Previous Status: Shut-In Well Name: University M LA #4

Status Change

Effective Date: 11/01/2007 API: 42-105-34736

Documentation:

☐ Phone Call From: _____ Title: _____ Date: _____

☒ Email From: Cheri Prince Title: _____ Date: 11/7/2017

☐ Field Inspection Date: _____

Comments:

see below

Chappell, Michelle

Subject: FW: Endeavor UL 75521 RRC 14455

Importance: High

From: Molina, Claudia

Sent: Monday, November 6, 2017 4:59 PM

To: Chappell, Michelle <mchappell@utsystem.edu>

Subject: FW: Endeavor UL 75521 RRC 14455

Importance: High

Hi Michelle!

As per Cherl Prince with Endeavor, the well below was shut in in our system 2/2006, however, they caught an error in their system and we noted they never reported production. The back to production date provided was 11/2007, so I will open up the reporting requirement as of that date.

Claudia G. Molina

432-686-4774

From: Cherl Prince [<mailto:cherl@eeronline.com>]

Sent: Monday, November 6, 2017 4:49 PM

To: Jana Couch <JCouch@eeronline.com>; Molina, Claudia <cmolina@utsystem.edu>

Subject: RE: UL 75521 RRC 14455

*** External Mail ***

But we didn't report that production – it wasn't caught until 2012.

Fortunately, the decks are the same so we went forward with the correct allocation.

From: Jana Couch

Sent: Monday, November 06, 2017 4:44 PM

To: 'Molina, Claudia' <cmolina@utsystem.edu>

Cc: Cherl Prince <cherl@eeronline.com>

Subject: RE: UL 75521 RRC 14455

Per Cherl Prince in our production department 11/01/2007

From: Cherl Prince

Sent: Friday, November 03, 2017 10:32 AM

To: Jana Couch

Subject: RE: Sent from Snipping Tool

So it looks like it should have come back on 11/01/07.

Jana Couch

Revenue Accountant

jcouch@eeronline.com

817-374-9378

