

Maurer, Michelle

From: Maurer, Michelle
Sent: Thursday, April 7, 2022 4:13 PM
To: Sawyer, Samantha; McGill, Justin; Barguiarena, Sonya
Cc: Cho, Oliver
Subject: University 10 3513HK 42-383-40689
Attachments: W-2 SUB IP University 10 3513HK 42-383-40689.pdf; Field Transfer University 10 3513HK 42-383-40689.pdf; As-Drilled 42-383-40689.pdf

Okay, so this well is a complete nightmare. This W-2 shows the well to be in the Lin (Wolfcamp), but then it will have a field transfer to the Spraberry (Trend Area) R 40 EXC, so that is where it should ultimately end up with the RRC # of 20685. The W-1 and W-2 showing that final field has not been filed by the operator yet. The perfs on the attached W-2 are incorrect, I was told they were supposed to be the ones on the As-drilled plat. The As-drilled plat has the wrong lease name. It is shown as the University 10 35-23 13HK. I was told this was an internal name and that it should be the University 10 3513HK. I have also requested an updated As-drilled plat. I hope you guys don't get as confused as I am! Thanks! Michelle