

Well Status Change

Current Status: _____ Operator: _____

Previous Status: _____ Well Name: _____

Status Change
Effective _____ API: _____

Documentation:

☐ Phone Call From: _____ Title: _____ Date: _____

☐ Email From: _____ Title: _____ Date: _____

☐ Field Inspection Date: _____

Comments:

Maurer, Michelle

Subject: FW: Wrage Energy - UL 101943 / RRC 18384 University 9A 2 42-461-34335

From: Dalton Linthicum <daltonjay12@icloud.com>
Sent: Friday, September 30, 2022 8:50 AM
To: Maurer, Michelle <mmaurer@utsystem.edu>
Subject: Re: Wrage Energy - UL 101943 / RRC 18384 University 9A 2 42-461-34335

****EXTERNAL MAIL****
This email originated outside of The University of Texas System Administration.
Please exercise caution when clicking on links or opening attachments.

June 2021 delayed production i just haven’t turned it on yet.

Black Diamond Endeavor
4774 North Chadbourne St San Angelo Tx, 76903

Dalton Linthicum

On Sep 22, 2022, at 8:00 AM, Maurer, Michelle <mmaurer@utsystem.edu> wrote:

Good morning Mr. Linthicum! We currently show the University 9A 2 as producing. I understand that it actually shut in. Please respond to this email and give me the exact shut in date (month/day/year) of the well, why it was shut in, (rod part, casing leak, etc.) and what your plans are for the well in the future. Thanks in advance! Michelle

Michelle Maurer | Regulatory Analyst | University Lands
P.O. Box 553 | Midland, TX 79702 | <http://www.utlands.utsystem.edu>
Main: 432.684.4404 | Direct: 432.686.4727 | mmaurer@utsystem.edu
Cell: 432-889-2114