

OPERATOR NAME AND ADDRESS including city, state and zip LIME ROCK RESOURCES IV-A, L.P. 1111 BAGBY STREET SUITE 4600 HOUSTON, TX, 77002		<b>OIL WELL STATUS REPORT</b> RAILROAD COMMISSION OF TEXAS Oil and Gas Division P.O. Box 12967 Austin, TX 78711-2967 Tracking 1671996 Status: Pending		Reason for Filing <input type="checkbox"/> Survey <input checked="" type="checkbox"/> Retest		Operator P-5 Organization 500794		RRC Dist. No. 08	
						Effective			

FIELD NAME * LEASE NAME	LEASE NO.	WELL NO	F- FLOWING P- PUMPING G- GAS LIFT S-	DATE TESTED MO/DAY/YR	OIL PRODUCED (BBL/DAY)	WATER PRODUCED (BBL/DAY)	GAS PRODUCED (MCF/DAY)
EMMA (CONNELL) UNIVERSITY 36	36879	6	PUMPING	01/15/2021	20.0 BBL	0 BBL	0 MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF
					BBL	BBL	MCF