

Maurer, Michelle

From: Wilson, Angie M <Angie.Wilson@conocophillips.com>
Sent: Thursday, May 20, 2021 7:22 AM
To: Maurer, Michelle; Maurer, Michelle; Shirley, Julia
Cc: Widmer, Sam A
Subject: University Andrews 116D
Attachments: UNAN 116D CHART 210511.pdf

****EXTERNAL MAIL****


This email originated outside of The University of Texas System Administration.
Please exercise caution when clicking on links or opening attachments.

This is to inform you that University Andrews 116D was repaired on 5/11/21. A passing H-5 was submitted and the current chart is attached. It will be put back in service as soon as the field comes back on. Please let me know if you have any questions. Thanks!

Angie Wilson

Angie Wilson | Regulatory Coordinator – Texas Permian | ConocoPhillips
O: 832-486-6145 | F: 918-662-4119 | PO BOX 2197 Houston, TX 77252

PRINTED IN U.S.A. 6 PM 7 8 9 10 11



TRAC 2025
257435
DATE 5-12-2021
BR 2221

Graphic Controls



LEASE Quiverty Andrews
WELL 116 D Lechat 4450
INFO Repair Posing 0
PRESSURE UP ON CSG 0
TO 5.20 5.30 5.30 5.30 5.30
FROM 5.30 5.30 5.30 5.30 5.30
CO. NAME Jose 05-11-21
UNIT 204 DATE Roberto Hernandez
DRIVER NAME