

OPERATOR NAME AND ADDRESS including city, state and zip LIME ROCK RESOURCES IV-A, L.P. 1111 BAGBY STREET SUITE 4600 HOUSTON,TX,77002	OIL WELL STATUS REPORT RAILROAD COMMISSION OF TEXAS Oil and Gas Division P.O. Box 12967 Austin, TX 78711-2967 Tracking 1211053 Status: Processed	Reason for Filing <input checked="checked" type="checkbox"/> Survey <input type="checkbox"/> Retest	Operator P-5 Organization 500794	RRC Dist. No. 08	W-10 <small>Rev.7/95 www-1</small>	Test Period: 11/2018 through 04/2019 Due Date: 05/01/2019 Effective 06/01/2019		
FIELD NAME * LEASE NAME	LEASE NO.	WELL NO	F- FLOWING P- PUMPING G- GAS LIFT S-	DATE TESTED MO/DAY/YR	OIL PRODUCED (BBL/DAY)	WATER PRODUCED (BBL/DAY)	GAS PRODUCED (MCF/DAY)	SHUT-IN X
SHAFTER LAKE, N. (SAN ANDRES) UL 14 CONWAY	45866	5H	PUMPING	04/02/2019	159.0 BBL	252 BBL	71 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 14 CONWAY	45866	1421H	PUMPING	04/07/2019	160.0 BBL	269 BBL	64 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 14 CONWAY	45866	2421H	PUMPING	04/03/2019	30.0 BBL	167 BBL	14 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 14 CONWAY	45866	3421H	PUMPING	04/09/2019	20.0 BBL	1730	8 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 14 CONWAY	45866	4421H	PUMPING	04/11/2019	30.0 BBL	890 BBL	13 MCF	
SHAFTER LAKE, N. (SAN ANDRES) FISHER 9B	45927	3H	PUMPING	04/01/2019	16.0 BBL	210 BBL	11 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 13 DOVER	46012	4H		04/15/2019	BBL	BBL	MCF	X
SHAFTER LAKE, N. (SAN ANDRES) UL 13 DOVER	46012	1126H	PUMPING	04/12/2019	18.0 BBL	298 BBL	8 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 13 DOVER	46012	2135AH	PUMPING	04/03/2019	29.0 BBL	594 BBL	13 MCF	
SHAFTER LAKE, N. (SAN ANDRES) UL 13 DOVER	46012	4426H	PUMPING	04/04/2019	25.0 BBL	1552	11 MCF	

CERTIFICATION: I declare under penalties prescribed in Texas Natural Resources Code, Sec.91.143., that I am authorized to make this report, that this report was prepared by me or under my supervision and direction, and that data and facts stated herein are true, correct, and complete to the best of my knowledge

Signature Sandra L Meche, Production Analyst
Title: Production Analyst
Phone: (713) 292-9527
Date: 04/15/2019

* AN ASTERISK PREPRINTED ON A SURVEY IDENTIFIES WELL SUBJECT TO COMMINGLING TEST REQUIREMENT

"X" AN "X" IS PLACED IN THE SHUT-IN BLOCK TO INDICATE THE WELL IS SHUT-IN