

Calculation Method Minimum Curvature
 Proposed Azimuth _____
 Dip Angle: _____
 Field Strength: _____

[illegible]

Railroad Commission of Texas
Oil & Gas Division
P.O. Box 12967
Capitol Station
Austin, Texas 78711

RE: DIAMONDBACK E&P LLC
UL BLK 6 DDU A #4007WA
SPRABERRY (TREND AREA)
Survey: 0 Abstract: 0
County: Midland
API #: 42-003-47995

To whom it concerns:

Please find the Surveys(s) and other information, required by your office, being submitted by RB Directional Services (P-5 No 685774) for the above referenced well.

Name:	Heather Sanders	Drain hole Number:	Original
Title:	Vice President	Type Survey:	MWD
Start Date:	19-Feb-19	Survey Start Depth:	106
End Date:	21-Feb-19	Survey End Depth:	1777

A certified plat with a Bottom Hole Location plotted on such plat. Data is oriented both to surface hole location and lease lines.
If any other information is required please contact RB Directional Services at the Footnote address and phone number.




RB Directional Services
PO Box 36
Water Valley, TX 76958
Ph. 432-254-2880
Email: rbdirectionalservices@gmail.com

RB Directional Services, LLC

Oil Company: DIAMONDBACK E&P LLC
Referenced Well: UL BLK 6 DDU A #4007WA
API #: 42-003-47995
County: ANDREWS
Dates Ran: From: 02/19/19 To: 02/21/19
Depths Ran: From: 106 To: 1777
Surveyor / Supervisor: John Wyatt

I, John Wyatt, certify that RB Directional Services supervised the taking of surveys on the above referenced well. The surveys on the dates stated, the data is true and correct, completed and within the limitations of the tool as set forth by RB Directional Services; that I am authorized and qualified to make this report and that I have reviewed this report and find it conforms to the principles and procedures as set forth RB Directional Services.



Surveyor