

## University O

## # 1A

5/26/2006 Unit cratered. Top joint, polish rod, liner, stuffing box & ppg tee replaced.  
6/15/2006  
6/25/2006  
9/01/2009  
2/07/2011  
12/16/2011  
1/05/2012  
5/17/2012  
3/01/2013  
7/01/2013  
12/28/2012 EMC: refuse bank and start well  
ticket:07829  
3/21/2013 Anchor test: test ok  
3/22/2013 No tbq leak found ( busted None ) Seat Nipple ?  
3/25/2013 compadre: pulled out 2" thread nipple broke inside of casing wellhead, replaced 2x4 p.c nipple  
ticket:109842  
3/28/2013 Compadre Roustabouts (110453) - We drove to location and lowered rod string until good tagg on bottom Filled up baird back pressure valve and  
cleaned up.  
3/29/2013 Compadre Roustabouts (110456) - We drove to location and lowered polish rod lines and tightened up loner head and balths. Filled up baird  
pressure valve took off spring and bolts.  
4/01/2013 compadre: cleaned up mess  
ticket:110120  
4/04/2013 compadre: we helped truck driver draining heater treater, pulled up water leg and inspection plate, cleaned up heater treater and water lefg and put  
back together  
ticket:110472  
4/05/2013 COMPADRE 110475 - Ran gas line from main gas into heater treater to pressure up heater treater.  
5/07/2013 COMPADRE 111702 - Raised rod string until light-tagging on bottom.  
5/09/2013 Pump plunger stuck in pump barrel ✓ Rig.  
5/14/2013  
5/15/2013 COMPADRE 111712 - Hooked up gasline from meter run into heater treater to pressure up heater treater. Replaced some fittings on wellhead.  
5/16/2013 COMPADRE 111717 - Replaced some connections on water tank pipe rison water line. (DUPLICATE 5/15)  
5/17/2013 EMC 22138: FOUND BLOWN FUSE AT TRANSFER BARK POLE. CHECKED MOTOR AND IS BURNT UP. (5/16/13 Invoice Date)  
5/23/2013 compadre 111736 - Lowered rod string until light tagging on bottom.  
6/18/2013 COMAPDRE 112234 - Pulled up 1" inch line come from meter and run into heater treater gas line.

July 22, 2013. Rig Work - Last time Pulled. from Billy W.



Energy Services

P.O. Box 255  
Snyder, TX 79550

FIELD TICKET 10 - 0010917

DATE 5-9-13

RIG NO. 11

CUSTOMER'S  
ORDER NO.

CONTRACT NO.

CUSTOMER

MAILING ADDRESS

CITY, STATE, ZIP

Endeavor Energy Resources

WELL INFORMATION

LEASE

COUNTY

WELL NO.

STATE

University '0' 1A  
Reagan TX

Work Performed

drove new rig to new location. Had a meeting. Rig up. Hoses head off. Checked to make sure pump was pumping. It didn't have good pumpation, it was stuck. Had trouble letting it loose. Finally succeeded. Went to vacuum when let it loose. Roels out all. Pull rod was stuck. Would for new pump. Enter in with pump rods. Hanged hoses head. Pumpation was good. Cleaned locale. Rig down. Shut down.

NO ACCIDENTS. NO INJURIES.

TRAVEL TIME

WORK TIME ON JOB

CO TIME

MISCELLANEOUS

From

A.M. P.M. to

A.M. P.M.

Unit No. 1

Crew Chief

Alexandro de la cruz

2

10

Derrick Man

Carlos O. Sierra Co.

2

10

Crew Man

Armando Cadena A.C.

2

10

Crew Man

Ramiro Diaz R.D.

2

10

Crew Man

ROD RECORD

TUBING RECORD

Swab Cups - Size

Sets

DO NOT WRITE IN THIS SPACE

Size No.

No. Jts.

Swab Cups - Size

Sets

Unit 10

Hrs. @ \$ 285

Per Hr. - \$ 2,850

5/8"

Size

O.S.R. - Size

Each

Hrs. @ \$

Per Hr. - \$

3/4" 146

Subs

Pipe Wiper - Size

Each

Extra Labor

Hrs. @ \$

Per Hr. - \$

7/8" 75

Tub Tongs ( ) Slip Inserts ( )

Travel Time 2

Hrs. @ \$ 285

Per Hr. - \$ 570

1" 63

Tub Dies ( ) Wireline Charge ( )

Co. Hyd. Tub Tongs 1

@ \$ 175

Per Day - \$ 175

Subs 1"

Seat Nip

Legal

Swab Cups

Sets @ \$

Per Set - \$

Misc. Info. (2)(3)(4)(6)

Mud Anc.

Misc.

O.S.R.

@ \$

each - \$

Misc.

Trips

@ \$

each - \$

Misc.

Highway Permits

- \$

Rod Pump

Make

Size

Number

Wiper Rubber

@ \$

each - \$

Pump Out

AS 56

Fishing Tools

- \$

Pump In

RHBC

2 1/2 x 1 1/4 x 6 x 2 AS 862

Sales Tax

- \$

Rig Foreman Approval

Customer

Juan Carlos Cruz  
Billy Wilha

TOTAL BILLING

- \$ 3,595

By signing this field ticket you acknowledge you represent the customer and you have read and agree to be bound by our terms and conditions on the back of this field ticket.



Energy Services  
P.O. Box 255  
Snyder, TX 79550

FIELD TICKET 10 - 0007325

CUSTOMER Endeavor Energy Resources

MAILING ADDRESS

CITY, STATE, ZIP

DATE 7-12-13

CUSTOMER'S  
ORDER NO.

RIG NO. 11

CONTRACT NO.

WELL INFORMATION

LEASE University O WELL NO. 1A  
COUNTY Reagan STATE TX

Work Performed Drove Rig to location. 10 minute JSA meeting. Spot Rig. Rig Up. Removed Unit's head. Released Pump. Set up equipment. Came out with Rods, laid down pump. Changed rod equipment to tubing. Unflanged Well. Released TAC. Came out with tubing to correct. Laid down Mud joint. Collected samples. Flange well. Shut down.



Energy Services  
P.O. Box 255  
Snyder, TX 79550

FIELD TICKET 10 - 0006764

CUSTOMER Endeavor

MAILING ADDRESS

CITY, STATE, ZIP

DATE 7-16-13

CUSTOMER'S  
ORDER NO.

RIG NO. 11

CONTRACT NO.

WELL INFORMATION

LEASE University O WELL NO. 1A  
COUNTY Upton STATE TX

Work Performed Drove crew to location, opened well, unflange well, picked up 1 mud joint, ran in new SN and a new 5 1/2 TAC, ran in 226 2 1/8 joints, landed tubing, set TAC with 16 points of tension, flange well, hook up flowline, then changed tools to run rod, secure well, shut down.



Energy Services  
P.O. Box 255  
Snyder, TX 79550

FIELD TICKET 10 - 0006765

CUSTOMER Endeavor

MAILING ADDRESS

CITY, STATE, ZIP

DATE 7-17-13

CUSTOMER'S  
ORDER NO.

RIG NO. 11

CONTRACT NO.

WELL INFORMATION

LEASE Univ. O WELL NO. 1A  
COUNTY Upton STATE TX

Work Performed Drove crew to location, open well, pick up new pump, ran in 34"-53, 718"-84, 1"-72, & 2-24 subs, 3-4ft subs, 1-6ft, land pump, respace well, hang well, check for pump action, guess pump action, standby to see if it pumped up, did not pump up, lowered well, standby to see if it pumped up again, called in, got orders to leave rig up and leave pumping overnight. Secure cables & well. Shutdown.

NO ACCIDENTS. NO INJURIES.

TRAVEL

WORK  
TIME

CO

MISCELLANEOUS



Energy Services  
P.O. Box 255  
Snyder, TX 79550

FIELD TICKET 10 - 0006766

CUSTOMER Endeavor

MAILING ADDRESS

CITY, STATE, ZIP

DATE 7-18-13  
CUSTOMER'S  
ORDER NO.

RIG NO. 11  
CONTRACT NO.

WELL INFORMATION

LEASE Univ. 0 WELL NO. 1A  
COUNTY Upton STATE TX

Work Performed Drove Crew to location check if well was pumping  
was pumping so we checked for Tag & was Tagging to  
Hard so we respected well & then changed well back on  
& left on Hard over 3 day wknd cause roads were too  
muddy to drive Rig ~~Down~~ Through we also left rig up in case  
it pumped off over wknd left open to Flowline shutdown.



Energy Services  
P.O. Box 255  
Snyder, TX 79550

FIELD TICKET 10 - 0007327

CUSTOMER Endeavor Energy Resources

MAILING ADDRESS

CITY, STATE, ZIP

DATE 7-22-13  
CUSTOMER'S  
ORDER NO.

RIG NO. 11  
CONTRACT NO.

WELL INFORMATION

LEASE Univ. 0 WELL NO. 1A  
COUNTY Reagan STATE TX

Work Performed drove to location had a 10 min meeting. Checked if  
well was pumping. Horses's head off ~~the~~ moved pot hole road.  
Set pump. & changed rod equip. to take out a tag. Tied back  
line to cable to handle weight unplugged well. Set TAC loose.  
Sealed a tag. Set TAC. put flange, put pumping T.  
Connected everything to free line. Had to let pump loose, went in  
vacuum, Lateral a rod & a two (1 in) Set pump. Put in a cable (1 mil),

NO ACCIDENTS. NO INJURIES.			TRAVEL TIME	WORK TIME ON JOB	CO TIME	MISCELLANEOUS
From	A.M. P.M. to	A.M. P.M.				
Unit No. <u>11</u>						<u>and 3 of (4) put released</u> <u>rod. Horses's head.</u> <u>Pumpation was good. Rig down</u> <u>cleared broken &amp; drive rig to differe</u> <u>well.</u>
Crew Chief <u>Alexandro delacruz A.D.</u>			<u>1</u>	<u>5</u>		
Derrick Man <u>Carlos O. Sierra C.O.S.</u>			<u>1</u>	<u>5</u>		